

## 金属片発見場所

6月6日15時現在

番号	発見日時		路線名	地名	距離標(KP)	片数(個)
1	6月2日	9:57	国道8号	小松市矢田野地内	353.73	2
2	"	10:59	"	加賀市熊坂地内	368.14	2
3	"	12:22	"	小松市平面地内	343.34	1
4	"	9:48	国道159号	河北郡津幡町地内	51.62	2
5	"	"	"	"	52.48	1
6	"	"	"	"	52.99	2
7	6月3日	9:53	国道159号	金沢市利屋町地内	55.14	1
8	"	11:30	"	羽咋市本江町地内	19.26	2
9	"	14:00	国道160号	七尾市万行町地内	2.06	1
10	"	14:15	"	七尾市沢野町地内	5.78	1
11	6月3日	14:30	国道159号	宝達志水町菅原地内	24.48	1
12	"	"	"	"	24.35	1
13	"	14:40	"	宝達志水町荻市地内	26.56	1
14	"	"	"	"	26.54	1
15	"	14:50	"	宝達志水町敷浪地内	28.49	1
16	"	14:20	国道160号	七尾市沢野町地内	6.59	1
17	"	14:30	"	七尾市庵地内	9.40	1
18	"	14:50	"	七尾市黒崎地内	15.04	1
19	"	15:00	"	"	15.43	1
20	"	"	"	"	15.46	1
21	"	"	"	"	15.48	1
22	"	15:10	"	七尾市大泊地内	18.62	1
23	"	"	"	"	18.80	1
24	6月4日	6:15	国道8号	金沢市森本町地内	310.30	3
25	"	14:05	"	津幡町坂戸地内	298.60	2
26	"	"	"	"	298.65	2
27	"	"	"	津幡町荒屋地内	302.18	1
28	"	14:50	"	白山市末正地内	335.30	1
29	"	14:26	"	能美市粟生地内	337.48	1
30	"	15:07	"	"	337.60	1
31	"	12:16	"	小松市本江町地内	345.40	1
32	"	9:15	"	小松市津波倉地内	350.91	1
33	"	9:23	"	"	350.98	1
34	"	"	"	"	350.98	2
35	"	9:45	"	"	351.03	1
36	"	9:55	"	小松市林町地内	351.68	1
37	"	9:57	"	"	351.80	1
38	"	10:00	"	"	351.96	2
39	"	11:22	"	"	352.55	1
40	"	11:24	"	"	352.55	1
41	"	11:03	"	小松市矢田野地内	353.80	3
42	"	17:02	国道157号	白山市長竹地内	8.41	1
43	"	18:59	"	白山市橋爪地内	9.01	1
44	"	18:58	"	"	9.02	1
45	"	18:54	"	野々市町清金地内	9.23	1
46	"	17:12	"	"	9.28	1
47	"	18:49	"	"	9.54	1
48	"	17:31	"	野々市町末松地内	10.85	1
49	"	18:34	"	"	10.85	1
50	"	17:40	"	白山市安養寺地内	11.84	1
51	"	14:38	国道159号	河北郡津幡町地内	51.37	1
52	"	14:57	"	金沢市利屋町地内	54.69	1
53	"	11:00	国道160号	七尾市黒崎地内	15.20	1
54	6月5日	10:40	国道8号	能美市小長野地内	341.15	1
					合計	67

片数(個):発見された金属片の個数